

Cornerstone Vocational Training Ltd

Risk Assessment

Reference: K02

Title	Fitting interior units	Date Of Assessment	Thu 04 Sep 2025
Site	Cornerstone Wirral	Location	70 Price Street
Risk Assessor	Brendan Bell	Assisted By	-
Non-Employees Involved	-	People At Risk	Visitors, Children & Young Persons, Service Users, Employees
Task Description	Fitting interior units		
Review Date	Thu 03 Sep 2026	Reviewer	Brendan Bell

Hazards

Hazard	Manual handling
Risk Of Harm	Assembled units range 300mm wide to 1000mm and all are 600mm deep and 720mm high. When moving or lifting there is a danger of musculoskeletal injury through using incorrect moving and lifting techniques.
Existing Control Measures	1. Work within a team of two to moving the assembled units. Follow manual handling techniques and always wear the correct PPE

Hazard	Repetitive Movements
Risk Of Harm	Units are connected together with Philips head screws which are tightened with a Philips screwdriver. The hinges on the doors are also fixed with Phillips head screws and fixed with a screwdriver. These actions may cause repetitive strain injuries
Existing Control Measures	1. Take regular breaks when connecting units and fixing the doors